
















DEKRA Automotive Solutions

Vehicle details

VIN	ZAMWS57B0 01173828	Brand	MASERATI	Maintenance date	-
Licence Plate	FB617GB	Model	Ghibli 3.0 V6 Ds 250cvAutomatica	Maintenance mileage	-
Registration date	16/10/2015	Year	2015	Exterior Color	Unknown
Odometer	106 671 km	Engine size	0	interior Color	Unknown
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	4	Gears	0		

Inspection Details

Inspection date	21/09/2017	Inspection loc.	FRATELLI ELIA LENTATE SUL SEVESO.		
					
					
					

Generic equipment

Automated air-conditioning	✓
Leather	✓
GPS system	✓
CD reader	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Electric seats	✓

Removable element

Spare wheel kit	✓
Triangle	✓







Technical Document

Spare key	✓
Remote key	✓
Title / License document	✓

Tyres

Pirelli 235/50/18 Y Summer 6.0 mm		Pirelli 235/50/18 Y Summer 6.0 mm	
Pirelli 235/50/18 Y Summer 4.0 mm		Pirelli 235/50/18 Y Summer 4.0 mm	

Exterior

1		Part	Bonnet	2		Part	Bumper
		Position	-			Position	Back
3		Damages	Stone impact	4		Damages	Scratched
		Severity	-			Severity	Length (cm) > 10
5		Repair mode	For info	6		Repair mode	Repair
		Part	Bumper			Part	Alloy wheel 18"
		Position	Front			Position	Back left
		Damages	Scratched			Damages	Scratched
		Severity	Length (cm) > 10			Severity	-
		Repair mode	Repair			Repair mode	Lumpsum repair
		Part	Alloy wheel 18"			Part	Alloy wheel 18"
		Position	Back right			Position	Front right
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumpsum repair			Repair mode	Lumpsum repair